



## Replaces Toro Greensmaster TriFlex 3420 Parts

*DPA Cutting Unit - Models 04613, 04614 & 04615*  
*Left-Hand Carbide Grooming Reel - 04708*



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Greensmaster TriFlex 3420 Parts



DPA Cutting Unit - Models 04613, 04614 & 04615  
Left-Hand Carbide Grooming Reel - 04708

| Item No | R&R Part No. | OEM Part No. | Description | Qty Req | Order Quantity |
|---------|--------------|--------------|-------------|---------|----------------|
|---------|--------------|--------------|-------------|---------|----------------|

**Blades**

|   |                  |          |                                              |    |  |
|---|------------------|----------|----------------------------------------------|----|--|
| 1 | <b>R110-2343</b> | 110-2343 | Groomer Blade - Carbide Tipped - Helix 1.5mm | 42 |  |
|---|------------------|----------|----------------------------------------------|----|--|

**Other Parts Available**

|    |                  |          |                                 |    |  |
|----|------------------|----------|---------------------------------|----|--|
| 20 | <b>R70-1350</b>  | 70-1350  | Spacer - 1/4 Fits Groomer Shaft | 82 |  |
| 21 | <b>R120-9653</b> | 120-9653 | Locknut - 7/8-14 Nylon Jam GR2  | 2  |  |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.