

Coupling - Compression w/Floloc 2 RG11220





Details

As cap is tightened, pressure causes the gripping ring to bite into the pipe eliminating pull out.

Specifications

Manufacturer

Flo Control

GA Power Equipment Spares 11 Sodium St Narangba, 4504 1300 363 004

https://rgs.rrproducts.com/