



NGK Spark Plug - ZFR5FGP RN7098



Replaces

Autolite	AP985
Bosch	FR8HPP30X, FR8LPP302X, FR8LPP30X
Champion	3318, 3318-2

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1