

3/4 PVC Union Split Nut Kit







Details

Split Nut Repair Kit is designed to replace broken union nuts on all True Union 2000 Ball Valves and Sch 80 Union 2000 fittings.

Kit includes: 2-Split Nut Halves 1-SS316 Gear Clamp. Full valve pressure rating maintained.

Specifications

Manufacturer Manufacturer's Model No

Spears SNK-007

GA Power Equipment Spares 11 Sodium St Narangba, 4504 1300 363 004

https://rgs.rrproducts.com/